

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
WASH,
20-6 LEW. V,
1-

Whitcomb Cabin
BZ Corners-Glenwood County Road
Conboy Lake National Wildlife Refuge
Glenwood Vicinity
Klickitat County
Washington

HABS No. WA-179

Alfred M. Staehli, Architect AIA, Photographer September 1985
Prints are 5"x7" enlargements of 2 1/4"x2 1/4" negatives

- | | |
|-----------|---|
| WA-179-1 | CONTEXTUAL VIEW, LOOKING NORTHEAST |
| WA-179-2 | WEST SIDE |
| WA-179-3 | NORTH SIDE |
| WA-179-4 | NORTHEAST CORNER, KITCHEN ADDITION, WITH MAIN HOUSE
ON RIGHT |
| WA-179-5 | EAST SIDE |
| WA-179-6 | SOUTH FRONT, KITCHEN ADDITION |
| WA-179-7 | SOUTHEAST CORNER, WITH PORCH OF KITCHEN ADDITION ON
RIGHT |
| WA-179-8 | SOUTH FRONT |
| WA-179-9 | DETAIL OF DOVETAIL LOG JOINTS, NORTHWEST CORNER |
| WA-179-10 | DETAIL OF KITCHEN ADDITION, SHOWING SIDING COPED TO
FIT LOG WALL OF MAIN HOUSE |
| WA-179-11 | FIRST FLOOR, EAST ROOM, DOORWAY TO WEST ROOM ON LEFT
AND BOTTOM OF STAIRWAY ON RIGHT |
| WA-179-12 | FIRST FLOOR, EAST ROOM, CHIMNEY ON FRAME PLATFORM |
| WA-179-13 | FIRST FLOOR, WEST ROOM, CLOSET UNDER STAIRS |
| WA-179-14 | SECOND FLOOR, WEST ROOM, TOP OF STAIRWAY IN
NORTHWEST CORNER |
| WA-179-15 | SECOND FLOOR, WEST ROOM, LOOKING SOUTHWEST |
| WA-179-16 | SECOND FLOOR, EAST ROOM, CHIMNEY AT EAST END |
| WA-179-17 | OUTBUILDING RUIN NORTHWEST OF HOUSE, LOOKING
NORTHEAST |
| WA-179-18 | OUTBUILDING RUIN NORTH OF HOUSE, LOOKING NORTH |